

Hot air iron set with safety rest

Item No: T0052711899N
Hot air iron set with safety rest

KEY FEATURES

- 100 W, 24 V
- Temperature range 50 °C to 550 °C
- Hot air flow ionic free
- Activated by finger switch

TECHNICAL DATA

ESD Safe	Yes
Hot Air (picto)	Yes
Maximum Hot Air Flow Rate l/min (Depends on Tool)	10 l/min
Power	100 W
Supply Unit	PUWAD101 WR2 WR3M WR3ME
Temperature Accuracy °C	± 26 °C
Temperature Accuracy °F	±26.66 °C
Temperature Range (Depends on Tool)	199 - 998°F
Temperature Range °C	93 - 537 °C
Temperature Range °F	199 - 998 °F
Tip Type	F R D & Q Series
UPC	037103308207