3M Automotive Aftermarket Division

Third Party Recommendations, Approvals, & Endorsements

		NUMBER: 23-029-07	
-		GROUP: Body	
Since Si	ULLETIN	DATE: July 17, 2007	1112
Jeep -	IL ETIN		1111
Transport		ter for mark 10 mm of the spatial and the spatial strategy of the spatial stra	
	includent of the oral states	an Ar Was Ar passing which which which we are and	1111
This Induity is excluded at or prevention, in pry here.	g by any results, she have		
Radio Speaker	Misdiagnosas - Human	bevorgen into with an improved	
ONT ONIEW:	and iter	lacing the door water site of reglacing any	
This bulletin if	wolves highlong located	lacing the door water shields with an improved in the tront door panels, and reglacing any	
damaged doo	r panel clips.		11111
			11111
MODELS:	(CS)	Padifica	
2004 - 2007		c or raitlis sounds coming from the doors when ds may be misinterpreted as speaker rattle.	
- anoto M	CONDITION:	c or radie sounds coming from the dours when ds may be misinterpreted as speaker ratifie.	
Some cusio	mers may experience sour	ids may be mismer pre-	11111
operating th	tadio of operations	Descripting	
DIAGNOS	IS:	ettom the Repair Procedure.	111111
If the symp	tom/colligition is a		
PARTSR	EQUIRED:	Description	111111
loty.	Part No.	- Walk (Front R)	*****
1	05152130AB	- A white Water (Front L)	
1	05152131AB		111111
1	06152128AB	Stield, Water (Rear 1.)	
1	05152129AB	Taon Flocked	
1	05019055AA	Cline Door Panel	
LAR-	06505759AA	- Lotina Door Panel	
AR AR	06505292AA	Cilps, Door Panel 3M Windo Weld (Ribbon Seder) of Equivalent (14 inch butyl) - 2 boxes with Equivalent (14 inch butyl) - 2 boxes with	1001 11
AR D	08610		W11 11
AH 12		service 1% vehicles 3M General Purpose Adhesive Cleaner or	
		3M General Forp	
AR	08987	a data	
L			
		THE PAR SERVICE	
		Stick with the Specialists	
		Stick with the	
1			
1			
L	and the second division of the second divisio		

Everyday, engineers and technicians around the world choose 3M products as the best solution for their manufacturing and repair needs. From Specifications and Endorsements to Service Bulletins and Recall Notices, 3M is proud to be a trusted partner of the Automotive Industry.

Here's just one example...



Reference Information

3MCollision.com

1-877-MMM-CARS (877-666-2277)

Organization:	Chrysler Group LLC	
Document		
Type:	Service Bulletin	
Name:	Radio Speaker Misdiagnosis – Rattle/Buzz Sounds in Door	
Number:	23-029-07	
Issued:	July 17, 2007	
Description		
Vehicles:	2004 – 2007 Pacifica	
Purpose:	Some customers may experience buzz or rattle sounds coming from the doors when operating the radio or CD. These sounds may be misinterpreted as speaker rattle.	
S Van D	This bulletin involves diagnosing and replacing the door water shields with an improved part, isolating the courtesy lamp located in the front door panels, and replacing any damaged door panel clips.	
Note:	3M provides this information for REFERENCE ONLY. ALWAYS refer to the original document or the OEM-provided model-specific collision damage repair manuals for complete instructions.	
3M Products:	PN08610 3M™ Windo-Weld Ribbon Sealer	
Included: Note:	 PN08610 3M™ Windo-Weld Ribbon Sealer In some cases, 3M may offer an alternate part number (different size/color) with the same chemistry and/or performance as the included product. Please consult your 3M Representative for more information. 	
Source:	www.MoparRepairConnection.com	
Source.	www.Collision.ALLDATA.com	
	Product Use: Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.	
	Warranty, Limited Remedy, and Disclaimer: Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.	
214	Limitation of Liability: Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.	
JM		
Building 0223-06-N-01 PI	<i>I</i> is a trademark of 3M. ease Recycle. Printed in the U.S.A. 3M 2012. All rights reserved.	