

# DEK SMT high performance understencil cleaning fabrics

DEK SMT high-performance understencil cleaning fabrics provide effective cleaning and compatibility with multiple print platforms.



## Features and benefits:

- Absorbent, vacuum-friendly & fast-wicking
  - Special non-woven fabric construction reduces lint, preventing aperture blockages and contamination
  - Fabric does not compromise vacuum power, optimizing aperture cleaning performance
  - Wicks consistently across the full width of the cleaning roll to ensure even distribution of the cleaning agent for a more productive clean
  - Wick time is extremely fast compared to other cleaning fabrics
- Effective cleaning
  - Dry cycle in addition to Wet (Vac/Dry) cycle
  - Delivers a superior clean for underside of the stencil
- Broad machine compatibility
  - Suitable for ASMPT, MPM, Ekra and other on-board cleaning systems, in addition to advanced understencil cleaners
  - 11 meters minimum length reduces number of changeovers and total changeover time on DEK platforms
  - 44 meter length available for latest MPM platform

DEK SMT HIGH PERFORMANCE UNDERSTENCIL CLEANING FABRICS							
Part number		Platform	Fabric width (mm)	Core width (mm)	Roll diameter (mm)	Inner core (mm)	Roll length (m)
SAP	DEK						
03127081	176215	ASMPT (DEK Micron)	515	530	56	19	11
03128524	176216	ASMPT (DEK Micron)	400	530	56	19	11
03128532	176217	ASMPT (DEK Micron)	300	530	56	19	11
03128523	173826*	ASMPT (DEK Micron)	515	530	56	19	11
03128538	431524	ASMPT (DEK Micron)	607	620	56	19	11
03233780		ASMPT (DEK Micron)	625				11
03217296	–	ASMPT (DEK TQ)	420	–	–	–	~ 22
03252411	–	ASMPT (DEK TQ L)	515	–	–	–	22
03252072	–	ASMPT (DEK TQ L)	580	–	–	–	22
03131502	173451	AP series, UP series, SPM, MPM125, Accela, Momentum	320	457	64	19	12
03131501	173450	AP series, UP series, SPM, MPM125, Accela, Momentum	443	457	64	19	12
03139825	178911	AP series, UP series, SPM, MPM125, Accela, Momentum	597	622	64	19	12
03131512	178864	Accela, Momentum	443	457	100	19	44
03144221	178909	Accela, Momentum	546	559	100	19	44
03128533	178908	All Ekra In - Line printers	400	400	53	13	10
03131513	178907	All Ekra In - Line printers	500	500	53	13	10

\*With metallised anti-static packaging.

# ASMPT

ASMPT Americas  
Phone: +888 768 4357 (press 2)  
Email: [smtparts.us@asmpt.com](mailto:smtparts.us@asmpt.com)

ASMPT Europe  
Phone: +40 722 692 108  
Email: [asmpt-psp.eu@asmpt.com](mailto:asmpt-psp.eu@asmpt.com)

ASMPT Asia  
Phone: +65 6750 3188  
Email: [SGstencils@asmpt.com](mailto:SGstencils@asmpt.com)



Process Support  
Products Website

[psp.smt.asmpt.com](http://psp.smt.asmpt.com)



Process Support  
Products Webshop

[smt.asmpt.com/en/  
myasmpt/webshop](http://smt.asmpt.com/en/myasmpt/webshop)



ASMPT SMT Solutions  
Website

[smt.asmpt.com](http://smt.asmpt.com)



ASMPT  
Website

[asmpt.com](http://asmpt.com)



ASMPT SMT Solutions  
YouTube

[www.youtube.com/c/  
ASMPTSMTSolutions](http://www.youtube.com/c/ASMPTSMTSolutions)

Edition 11/07/2024 | All rights reserved. | Order No.: A22-ASMPT-A322-EN | Printed in Germany | © ASMPT GmbH & Co. KG

All information and illustrations in this brochure are provided "as is" and without any warranties of any kind, whether expressed or implied, including but not limited to, implied warranties of satisfactory quality, fitness for a particular purpose and/or correctness.

The contents of this brochure are for general information purposes only, do not constitute advice, and are subject to change without notice. ASMPT therefore makes no warranties or representations regarding the use of the content, details, specifications or information contained in this brochure in terms of their correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise, in each case to the fullest extent permitted by law. Please contact ASMPT for the most current information. Any specific performance features and/or capabilities will only be binding if contractually agreed upon.

All product names are brands or trademarks of ASMPT or other suppliers. Unauthorised use by third parties may violate the rights of their owners.