










# 729 Pro Automatic Pressure Calibrator

[www.fluke.com](http://www.fluke.com)



## Display



### Lower Display Measure Volts

VDC

Up to 30 V

Device Under Test

### Measure RTD

RTD Probe

### Temperature Units

07/28/2020 01:47 pm

Measure 7000kPa Max Gauge

0.01 psi

Setpoint 0.00

Step Size 0.15

Measure VDC 1.003 V 0.1 %

Measure Temperature 99.98 °C

138.500 Ω

1 F4

2 °F / °C

### Batteries

1

2

### USB

USB Port

### Tasks

1 TASKS

01/18/2017 06:28 am 0.131 psi

Tasks

1. Pressure Transmitter (P/I)
2. Pressure Switch (SW)
3. Current to Pressure Test (I/P)
4. Pressure Leak Test
5. Pressure Transmitter (P/V)
6. Pneumatic Pressure Transmitter (P/P)

Downloaded Tasks Custom Tasks Resume Tasks

7 8 9

4 5 6

1 2 3

+ 0 -

### Set Language

1 SETUP

2 2 /

3 ENTER

4 English 简体中文

5

6 English 简体中文

7 ENTER

### Drain Water

### Pressure Module