



PART NUMBER - CABLE-RWLMOD

Water Level Sensor Cable for RXMOD-W1

Provides the connection between the HOBO RX3000 Remote Monitoring Station and the water level sensor.

IMPORTANT INFORMATION

HOBO RX3000, RXMOD-W1, or MX2001-0x-Ti-S are required.

Overview

Provides the connection between the HOBO RX3000 Remote Monitoring Station and the water level sensor. A <u>HOBO RX3000</u> station, a water level sensor module (<u>RXMOD-WI</u>), and a water level sensor (<u>MX2001-0x-Ti-S</u>) are required for use with this cable.

Cables can be ordered in lengths from 1 meter to 400 meters for deployment in a wide range of applications. The 1-, 2-, 5-, 10-, 15-, 30-, and 60-meter cable lengths are standard and typically in stock. Custom cable lengths require a lead time of one to two weeks.

PLEASE NOTE: Custom cables are ineligible for return.

Features

- Interchangeable Kevlar-reinforced cable can be used to suspend sensor
- · Provides sensor communication and power
- Two O-rings in the water level sensor connector ensure a long-term waterproof seal
- · Cables are easy to attach or change

What's In The Box

Water level cable

- Select -

Standard Lengths

1.0m Cable (CABLE-RWLMOD-1.0)

2.0m Cable (CABLE-RWLMOD-2.0)

5.0m Cable (CABLE-RWLMOD-5.0)

010m Cable (CABLE-RWLMOD-010)

015m Cable (CABLE-RWLMOD-015)

030m Cable (CABLE-RWLMOD-030)

060m Cable (CABLE-RWLMOD-060)

Most Popular Custom Lengths

0.4m Cable (CABLE-RWLMOD-0.4)

0.6m Cable (CABLE-RWLMOD-0.6)

1.2m Cable (CABLE-RWLMOD-1.2)

1.4m Cable (CABLE-RWLMOD-1.4)

1.6m Cable (CABLE-RWLMOD-1.6)

1.8m Cable (CABLE-RWLMOD-1.8)
3.0m Cable (CABLE-RWLMOD-3.0)

J.OH Cable (CABLE RWENIOD J.O,

4.0m Cable (CABLE-RWLMOD-4.0)

11m Cable (CABLE-RWLMOD-011)