

ACCESSORIES

All devices



Extended test lead XTL30

30 m
Item no. 2007-997

Extended test lead XTL50

50 m
Item no. 2007-998



Three-phase current adapter 16A

DE-CEE16-S (plug)
Item no. DE-060

Three-phase current adapter 32 A

DE-CEE32-S (plug)
Item no. DE-061



Accessory bag

Item no. 1007-463



Test lead set CAT IV 600 V

(standard 3 wire lead set with un-fused probes and clips),
Item no. 1001-99



Test & carry pouch

(Dimensions: approx. 240 x 160 x 70mm),
Item number 1006-408

Test lead set CAT IV 600 V

(with fuses 10A F, 600 V, especially for energy suppliers & public utilities,
Item no. 1001-975

only MFT1835 & MFT1845+




MCC1010 (ICLAMP)

CAT IV 600 V
Item no. 1010-516



MVC1010 (VCLAMP)

CAT IV 600 V
Item no. 1010-518



Earth Test Spike Kit

3 pcs. (4 m, 10 m, 15 m),
with two earth spikes,
Item no. 1001-810



50m Earth Test Cables, Spikes & Clamps Kit

Earth measuring cables (2 x 50M & 2 x 30M) ground spikes and clamps,
Item number 1010-179

EVCA210 (only MFT1845+)



EVCA210

Test adapter for charging stations,
Item no. 1013-317

