



PROSTAT® PMT-872 Wrist Strap/Footwear Checker

The PMT-872 is a unique, highly portable, battery operated multifunction PASS/FAIL performance verifier. It confirms the operational resistance range of wrist straps, heel straps and ESD controlled footwear. The PMT-872 features a large test button, audible PASS BEEP with Green PASS light, Red LOW and HIGH Fail lights, and yellow battery low indicator. Additional connections are provided for an optional AC-DC Power adapter and for testing **dual conductor wrist straps**. A front panel toggle switch allows testing of wrist straps <u>and</u> footwear at one station. A footwear test plate, snap connector, and lead can be purchased separately.

PMT-872 WRIST STRAP/FOOTWEAR CHECKER SPECIFICATIONS

Test Voltage & Current: Nominal 9 volts and 0.006 µA to 1.0 mA

Power: One (1) standard 9-volt battery, PROCELL, Eveready #216 (NEDA 1604, JIS 006P, IEC 6F22);

or, Optional AC/DC converter.

Factory Adjusted Measurement Ranges & Accuracy:

WRIST STRAPS: 8.0×10^5 Ohms to 1.0×10^7 Ohms $\frac{\pm 5\%}{5\%}$ (Factory Default) **FOOTWEAR:** 8.0×10^5 Ohms to 1.0×10^8 Ohms $\frac{\pm 5\%}{5\%}$ (Factory Default)

WRIST STRAPS: 8.0×10^5 Ohms to 3.5×10^7 Ohms < $\pm 5\%$ **FOOTWEAR:** 8.0×10^5 Ohms to 3.5×10^7 Ohms < $\pm 5\%$

Toggle Range Selection: **UP** for Wrist Straps and **DOWN** for Footwear

Push Button: 27 mm Diameter, Metal spring loaded

Light Indicators: Vertically Oriented. From Top to Bottom:

FAIL High: Red LED

PASS: Green LED with Audible Buzzer

FAIL Low: Red LED

BATTERY LOW: Yellow LED (At <8.2V Battery Voltage)

Audible Signal: Fast, Individual "Beeping" Sound with Green PASS LED on.

Operating Range: 5°C to 49°C (40°F to 120°F) Storage Temp: -15°C to 60°C (5°F to 140°F)

Relative Humidity: 0% to 90% Battery Life: 40 hours typical

Dimensions: 115 mm x 69 mm x 26 mm

Weight: 6 oz.