ELECTRICAL TEST TOOLS

PHASE AND MOTOR ROTATION METERS

MODELS 6608, 6609 & 6610

Ideal for installing rotating machinery or motors, and for checking generator output phase direction

SPECIFICATIONS

MODELS	6608	6609	6610	
ELECTRICAL				
Operating Voltage	40 to 850Vac between phases	With leads connected: 40 to 600Vac between phases	Static induction	
Frequency Range	15 to 400Hz		45 to 65Hz	
Power Supply	Self-powered via the measurement inputs	9V Alkaline battery (included)	One 9V Alkaline battery (included)	
MECHANICAL				
Dimensions	5.1 x 2.7 x 1.3" (130 x 69 x 32mm)		5.0 x 2.8 x 1.8" (128 x 72 x 44mm)	
Weight	4.5oz (130g)	6oz (170g)	13.4oz (380g) battery included	
ENVIRONMENTAL				
Operating Temperature	32° to 104°F (0° to 40°C)		14° to 122°F (-10° to 50°C); max, 80% RH	
Storage	-4° to 122°F		-4° to 140°F	
Temperature	(-20° to 50°C); < 80% RH		(-20° to 60°C); max. 80% RH	
SAFETY				
Safety Ratings	IEC 61010-1, DIN VDE 0411; IEC 61557-7, DIN VDE 0413-7; Tightness: IP40		EN 61010-1, EN 61326-1	
Electrical Safety	600V CAT III		1000V CAT III; 600V CAT IV	

PRODUCT INCLUDES

6608 & 6609

Carrying case, three test leads (4ft), three alligator clips and a user manual.

6610

Soft carrying case, meter with attached test leads (black, red & blue) with alligator clips, 9V battery and user manual.















(Model 6610 Only)

FEATURES

- Voltage sensing detector clips no metal contact points to promote greater safety (Model 6610)
- Indication of live phase presence or phase absence
- Designed for checking a wider range of 3-phase power source from 75V to 1000VAC (Model 6610)
- Determination of a motor's rotation direction (Model 6609)
- Automatic testing as soon as the instrument is connected
- Terminals and cables identified by colorcoding to simplify connection (test leads are attached to Model 6610)
- Phase rotation indicators (Model 6608)
- Phase and motor rotation indicators (Models 6609 & 6610)
- Color-coded leads (red, black, blue) and alligator clips (black)
- Color-coded jacks for common U.S. phase colors
- Line supplied no battery needed (Model 6608)
- Protected internally by high impedance circuit to limit the current to user safe limits

CATALOG NO.	DESCRIPTION
2121.10	Phase Rotation Meter Model 6608
2121.11	Phase & Motor Rotation Meter Model 6609
2121.12	Phase Rotation Meter Model 6610 (Non-contact)

