

TECHNICAL DATA

2627-S | Spare Sensor Kit with Standard-Accuracy Sensor





Product overview: 2627-S | Spare Sensor Kit with Standard-Accuracy Sensor

One of the potential advantages of a digital thermo-hygrometer is that instead of sending the entire unit out for calibration, you can simply swap sensors and send only the sensors due for calibration out of the lab. The 1620A "DewK" Thermo-Hygrometer allows you to swap sensors without shutting it down or discontinuing your other readings.

Smart sensors make this possible because all of the calibration information is contained inside the sensor. Your costs are reduced because the 1620A never needs to be calibrated since it is only a display. Spare sensors like the 2627-S are less expensive to store, ship and recalibrate than an extra chart recorder.

With each kit you get a:

- Standard-accuracy sensor
- Sensor wall mount bracket
- 7.6 m (25 ft) extension cable

Ordering information



2627-S

Spare Sensor Kit with Standard-Accuracy Sensor

Fluke. *Keeping your world up and running.®*

Fluke Corporation
PO Box 9090, Everett, WA 98206 U.S.A.

For more information call:
In the U.S.A. (800) 443-5853
In Canada (800) 36-FLUKE
From other countries +1 (425) 446-5500
www.fluke.com

©2025 Fluke Corporation.
Specifications subject to change without notice.
04/2025

**Modification of this document is not permitted
without written permission from Fluke
Corporation.**