

# 3540 FC **3 Phase Power Monitor**

## Safety Information



2-Year Limited Warranty. See the Users Manual for the full warranty.

Go to www.fluke.com to register your Product, read the User Manual, and find more information.

A Warning identifies conditions and procedures that are dangerous to the user.

#### A Marnings

To prevent possible electrical shock, fire, or personal injury:

- · Read all safety information before you use the Product.
- · Use the Product only as specified, or the protection supplied by the Product can be compromised.
- Comply with local and national safety codes. Use personal protective equipment (approved rubber gloves, face protection, and flame-resistant clothes) to prevent shock and arc blast injury where hazardous live conductors are exposed.
- · Examine the case before you use the Product. Look for cracks or missing plastic. Carefully look at the insulation around the terminals.
- Replace the mains power cord if the insulation is damaged or if the insulation shows signs of wear.
- Use Product-approved measurement category (CAT), voltage, and amperage rated accessories (probes, test leads, and adapters) for all measurements.

PN 4798971 July 2016

©2016 Fluke Corporation. All rights reserved. Specifications are subject to change without notification. All product names are trademarks of their respective companies.

Fluke Corporation P.O. Box 9090 U.S.A.

Fluke Europe B.V. P.O. Box 1186 The Netherlands

ООО «Флюк СИАЙЭС» 125167, г. Москва, Everett, WA 98206-9090 5602 BD Eindhoven Ленинградский проспект дом 37, корпус 9, подъезд 4, 1 этаж

- Do not use test leads if they are damaged. Examine the test leads for damaged insulation and measure a known voltage.
- Do not use the Product if it is damaged.
- The battery door must be closed and locked before you operate the Product.
- · Do not work alone.
- Use this Product indoors only.
- Do not use the Product around explosive gas, vapor, or in damp or wet environments.
- Use only the external mains power supply included with the Product.
- Do not exceed the Measurement Category (CAT) rating of the lowest rated individual component of a Product, probe, or accessory.
- Keep fingers behind the finger guards on the probes.
- Do not touch voltages >30 V ac rms, 42 V ac peak, or 60 V dc.
- Do not use a current measurement as an indication that a circuit is safe to touch. A voltage measurement is necessary to know if a circuit is hazardous.
- Do not apply more than the rated voltage, between the terminals or between each terminal and earth ground.
- Measure a known voltage first to make sure that the Product operates correctly.
- De-energize the circuit or wear personal protective equipment in compliance with local requirements before you apply or remove the flexible current probe.
- Remove all probes, test leads, and accessories before the battery door is opened.
- Do not use USB accessories when the Product is installed in environment with wires or exposed metal parts with hazardous live voltage such as in cabinets.
- · Do not operate the touch screen with sharp objects
- Do not use the Product if the protection film on the touch panel is damaged.
- Do not touch the metal parts of one test lead when the other is still connected to hazardous voltage.
- · Do not short the battery terminals together.
- Do not disassemble or crush battery cells and battery packs.
- Do not put battery cells and battery packs near heat or fire. Do not put in sunlight.
- Disconnect the battery charger and move the Product or battery to a cool, non-flammable location if the rechargeable battery becomes hot (>50 °C) during the charge period.
- Have an approved technician repair the Product.

#### ▲ Caution

 Replace the rechargeable battery after 5 years of moderate use or 2 years of heavy use. Moderate use is defined as recharged twice a week. Heavy use is defined as discharged to cutoff and recharged daily.

#### Symbols

Symbol	Description
⚠	WARNING. RISK OF DANGER.
Δ	WARNING. HAZARDOUS VOLTAGE. Risk of electric shock.
Ĩ	Consult user documentation.
	Double Insulated
Ŧ	Earth
•	Battery
CATI	Measurement Category II is applicable to test and measuring circuits connected directly to utilization points (socket outlets and similar points) of the low- voltage MAINS installation.
САТШ	Measurement Category III is applicable to test and measuring circuits connected to the distribution part of the building's low-voltage MAINS installation.
САТ 🛙	Measurement Category IV is applicable to test and measuring circuits connected at the source of the building's low-voltage MAINS installation.
CE	Conforms to European Union directives.
Cus	Certified by CSA Group to North American safety standards.
	Conforms to relevant South Korean EMC standards.
Ò	Conforms to relevant Australian EMC standards.
Li-ion	This product contains a Lithium-ion battery. Do not mix with the solid waste stream. Spent batteries should be disposed of by a qualified recycler or hazardous materials handler per local regulations. Contact your authorized Fluke Service Center for recycling information.
X	This product complies with the WEEE Directive marking requirements. The affixed label indicates that you must not discard this electrical/electronic product in domestic household waste. Product Category: With reference to the equipment types in the WEEE Directive Annex I, this product is classed as category 9 "Monitoring and Control Instrumentation" product. Do not dispose of this product as unsorted municipal waste.

### Safety Specifications

3 Phase Power Monitor			
Operating temperature 0 °C to 45 °C (+32 °F to +113 °F)			
Storage temperature20 °C to +60 °C (-4 °F to +140 °F)			
Operating Humidity	<10 °C (<50 °F) non condensing 10 °C to 30 °C (50 °F to 86 °F) ≤95 % 30 °C to 40 °C (86 °F to 104 °F) ≤75 % 40 °C to 45 °C (104 °F to 113 °F) ≤45 %		
Altitude			
Operating	2000 m		
Storage	12 000 m		
Battery	Li-ion 3.7 V, 9.25 Wh, customer- replaceable		
Operating temperature	0 °C to 45 °C (32 °F to 113 °F)		
Storage temperature	-20 °C to +50 °C (-4 °F to +122 °F)		
Charge	0 °C to 45 °C (32 °F to 113 °F)		
Safety			
General	IEC 61010-1: Pollution Degree 2		
Measurement	IEC 61010-2-033: CAT IV 600 V / CAT III 1000 V		
Mains Input	Overvoltage Category II, Pollution Degree 2		
Voltage Terminals	Overvoltage Category IV, Pollution Degree 2		
Li-ion Battery	IEC 62133		
Electromagnetic Compatibility (EMC)			
International	IEC 61326 1: Industrial		

International..... IEC 61326-1: Industrial

CISPR 11: Group 1, Class A

Group 1: Equipment has intentionally generated and/or uses conductively-coupled radio frequency energy that is necessary for the internal function of the equipment itself.

Class A: Equipment is suitable for use in all establishments other than domestic and those directly connected to a lowvoltage power supply network that supplies buildings used for domestic purposes. There may be potential difficulties in ensuring electromagnetic compatibility in other environments due to conducted and radiated disturbances.

Emissions that exceed the levels required by CISPR 11 can occur when the equipment is connected to a test object.

Korea (KCC).....Class A Equipment (Industrial Broadcasting & Communication Equipment)

Class A: Equipment meets requirements for industrial electromagnetic wave equipment and the seller or user should take notice of it. This equipment is intended for use in business environments and not to be used in homes.

USA (FCC) ...... 47 CFR 15 subpart C.

Wireless Radio with Adapter

Frequency Range...... 2412 MHz to 2462 MHz

Output Power ...... <100 mW