WARNING!

The HAKKO 98O is a 20 watt soldering tool for light to medium duty applications. The switch on top of the iron turns on the 130 watt feature, for occasional heavy duty soldering.

FOR YOUR SAFETY...
DO NOT HOLD THE HIGH HEAT
SWITCH 'ON' FOR MORE THAN
30 SECONDS!
FAILURE TO HEED THIS
WARNING WILL CAUSE THE IRON
HOUSING TO MELT!



DON'T...

HIT THE IRON AGAINST A HARD OBJECT..

You could break the ceramic heater.

USE A FILE ON THE TIP.

You could destroy the tip.


CAUTION:

-The tip and heater tube will be VERY HOT when the iron is plugged in.

HELPFUL HINTS:

- Clean the pieces to be soldered first. This will help to ensure good joints.
- Always prepare (tin) the tip before soldering.
- Always coat the tip after soldering.
- Heat the parts you are going to solder before you apply the solder for better flow and stronger joints.
- Don't leave the iron in contact with the joint any longer than is necessary for proper solder flow.
- Don't move the assembled parts until the solder has cooled.
- We recommend using the largest tip possible for each application.

It's a good idea to have a holder and cleaner for your HAKKO iron. We recommend the HAKKO 602, below.



LAC ENT S AIL

ABLE
FOR THE HAKKO P980:
Point: 980-T-B (Standard)
Bevel: 980-T-BC
Chisel: 980-T-D

For more information on HAKKO products, contact:

25072 Anza Dr.

**Phone: (805) 294-0090 Fax: (805) 294-0096

Toll free: 1-800-88-HAKKO

国计例图