



PART NUMBER - AC-SENS-1

AC Power Adapter for 3rd Party Sensors

up to 400mA @12vdc

An AC power adapter that provides DC power to sensors that require it, expanding the range of 3rd-party sensors that can be used with Onset's HOBO RX3000, U12, U30-NRC, and ZW series products.

Overview

An AC power adapter that provides DC power to sensors that require it, expanding the range of 3rd-party sensors that can be used with Onset's HOBO RX3000, U12, U30-NRC, and ZW series products.

Input: 100-240VAC @ 50/60Hz 0.2A

Output: 12VDC @ 0.5A

Specifications

Input: 100-240VAC @ 50/60Hz 0.2A

Output: 12VDC @ 0.5A

Compatible Items

Web-based Monitoring Systems - via remote communication

RX3000 Remote Monitoring Station

RX3000

USB Data Loggers - requires external sensor(s)

HOBO U30 USB Weather Station

U30-NRC

HOBO 4-Channel Analog Data Logger

UX120-006M

USB Data Loggers - w/external sensor(s)

HOBO U30 USB Weather Station Starter Kit

U30-NRC-SYS-C