Packing List



INSTRUCTION MANUAL



Brass Wool for B-IRON Charging-Base 1 unit



0-0608000

Manual 1 unit Ref. 0028090





CL0300 Brass Wool for

B-IRON Charging-Base

Brass Wool CL0300 is used with JBC's B·IRON Charging-Bases.

The brass wool is a very effective cleaning method. It leaves a thin layer of solder on the tip preventing oxidation between cleaning and tinning.

www.jbctools.com





Wool Replacement

Lift the wiper by using the recess on the edge and disassemble it.



Replace the wool for a new one and reassemble the wiper. Make sure that the wiper is correctly inserted all around



Leave space

