# Keysight U1700 Series Handheld LCR Meters

Data Sheet



Test passive components conveniently, affordably and reliably with the Keysight U1700 Series LCR meters—extending the tradition of industry-leading benchtop units



## Introduction

The Keysight Technologies, Inc. U1700 Series handheld LCR meters expand Keysight's portfolio of handheld tools into electronics assembly and passive components troubleshooting. Better yet, these handheld models extends the tradition of Keysight's industry-leading benchtop units to more affordable and portable forms. Keysight's latest handheld LCR meters in all-new orange offer capabilities and functionalities equivalent to the A models.

### No waiting for quick, basic LCR tests

Sharing a bench LCR meter is practical, but isn't always convenient. With Keysight's new line of handheld LCR meters, you can perform quick, basic LCR measurements at your convenience. Now that they're available at a lower price point compared to traditional benchtop units, everyone on your team can be equipped for passive-component testing-on the bench or on the go-without the wait.

## Uncompromised quality and reliability

The handheld LCR meters are housed in robust overmold and tested to stringent industrial standards.

### Features

- 20,000 counts resolution
- Dual display with backlight (for U1732A/U1732B)
- Wide LCR ranges with 2 to 4 selectable test frequencies
- Auto-calculation of phase angle (for U1732A/U1732B), dissipation factor and quality factor
- Tolerance mode: 1%, 5% and 10% (20% with U1732A/U1732B)
- Relative mode
- Hold and Min/Max/Average recordings
- Data logging to PC with optional IR-to-USB cable



continuous readings when you hook the

# Take a closer look



Figure 2: U1732B front view

# U1731A/U1731B Electrical Specifications

Accuracy is expressed as  $\pm$  (% of reading + number of least significant digits) at 23 °C ±5 °C and <75% R.H.

# Resistance (Parallel Mode), Test Frequency = 120 Hz/1 kHz

		Accui	racy	
Range	Maximum Display	@ 120 Hz	@ 1 kHz	Note
10 ΜΩ	9.999 MΩ	2.0% + 8	2.0% + 8	After open cal.
2000 kΩ	1999.9 kΩ	0.5% + 5	0.5% + 5	After open cal.
200 k <b>Ω</b>	199.99 kΩ	0.5% + 3	0.5% + 3	-
$20~\text{k}\Omega$	19.999 k $\Omega$	0.5% + 3	0.5% + 3	-
2000 Ω	1999.9 Ω	0.5% + 3	0.5% + 3	-
200 Ω	199.99 Ω	0.8% + 5	0.8% + 5	After short cal.
20 Ω	$19.999\Omega$	1.2% + 40	1.2% + 40	After short cal.

Specifications are based on measurements performed at the test sockets and on battery operation.
 DUT and test leads need to be properly shielded by connecting to the guard terminal, if necessary.

# Capacitance (Parallel Mode), Test Frequency = 120 Hz

	Accuracy		_	
Range	Maximum Display	Capacitance	DF	Note
10 mF	19.99 mF <sup>1</sup>	3.0% + 5 (DF<0.1)	10% + 100/Cx + 5 (DF<0.1)	After short cal.
1000 μF	1999.9 μF <sup>2</sup>	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After short cal.
200 μF	199.99 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
20 μF	19.999 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
2000 nF	1999.9 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
200 nF	199.99 nF	0.7% + 5 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	After open cal.
20 nF	19.999 nF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After open cal.

## Capacitance (Parallel Mode), Test Frequency = 1 kHz

		Acc	Accuracy	
Range	Maximum Display	Capacitance	DF	Note
1 mF	1.999 mF <sup>1</sup>	3.0% + 5 (DF<0.1)	10% + 100/Cx + 5 (DF<0.1)	After short cal.
200 μF	199.99 μF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After short cal.
20 μF	19.999 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
2000 nF	1999.9 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
200 nF	199.99 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
20 nF	19.999 nF	0.7% + 5 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	After open cal.
2000 pF	1999.9 pF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After open cal.

<sup>1.</sup> This reading can be extended up to 1999 MAX display with accuracy that is not

<sup>2.</sup> This reading can be extended up to 19999 MAX display with accuracy that is not specified.

Q value is the reciprocal of DF.
 Cx = Counts of displayed C value. E.g., If C = 88.88 μF then Cx = 8888.

<sup>5.</sup> Specifications are based on measurements performed at the test sockets and on battery operation.

<sup>6.</sup> DUT and test leads need to be properly shielded by connecting to the guard terminal, if necessary.

# Inductance (Series Mode), Test Frequency = 120 Hz

		Accu	Accuracy		
Range	Maximum Display	Inductance	DF	Note	
1000 H	999.9 H	1.0% + (Lx/10000)% + 5	2.0% + 100/Lx + 5	After open cal.	
200 H	199.99 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-	
20 H	19.999 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-	
2000 mH	1999.9 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-	
200 mH	199.99 mH	1.0% + (Lx/10000)% + 5	3.0% + 100/Lx + 5	After short cal.	
20 mH	19.999 mH	2.0% + (Lx/10000)% + 5	10.0% + 100/Lx + 5	After short cal.	

# Inductance (Series Mode), Test Frequency = 1 kHz

		Accu	Accuracy	
Range	Maximum Display	Inductance	DF	Note
100 H	99.99 H	1.0% + (Lx/10000)% + 5	2.0% + 100/Lx + 5	After open cal.
20 H	19.999 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
2000 mH	1999.9 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
200 mH	199.99 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
20 mH	19.999 mH	1.0% + (Lx/10000)% + 5	3.0% + 100/Lx + 5	After short cal.
2000 μΗ	1999.9 μΗ	2.0% + (Lx/10000)% + 5	10.0% + 100/Lx + 5	After short cal.

Q value is the reciprocal of DF.
 Lx = Counts of displayed L value. E.g., If L = 88.88 H then Lx = 8888.

<sup>3.</sup> Specifications are based on measurements performed at the test sockets and on battery operation.

4. DUT and test leads need to be properly shielded by connecting to the guard

terminal, if necessary.

# U1732A/U1732B Electrical Specifications

Accuracy is expressed as ± (% of reading + number of least significant digits) at  $23 \,^{\circ}\text{C} \pm 5 \,^{\circ}\text{C}$  and  $<75\% \, \text{R.H.}$ 

# Resistance (Parallel Mode), Test Frequency = 100 Hz/120 Hz

		Acci	ıracy	
Range	Maximum Display	@ 100 Hz	@ 120 Hz	Note
10 ΜΩ	9.999 MΩ	2.0% + 8	2.0% + 8	After open cal.
2000 kΩ	1999.9 kΩ	0.5% + 5	0.5% + 5	After open cal.
200 kΩ	199.99 kΩ	0.5% + 3	0.5% + 3	-
$20~\text{k}\Omega$	19.999 k <b>Ω</b>	0.5% + 3	0.5% + 3	-
2000 Ω	1999.9 Ω	0.5% + 3	0.5% + 3	-
200 Ω	199.99 Ω	0.8% + 5	0.8% + 5	After short cal.
20 Ω	$19.999\Omega$	1.2% + 40	1.2% + 40	After short cal.

# Resistance (Parallel Mode), Test Frequency = 1 kHz/10 kHz

		Acc		
Range	Maximum Display	@ 1 kHz	@ 10 kHz	Note
10 ΜΩ	9.999 MΩ	2.0% + 8	3.5% + 10	After open cal.
2000 kΩ	1999.9 kΩ	0.5% + 5	2.0% + 10	After open cal.
200 kΩ	199.99 kΩ	0.5% + 3	1.5% + 5	-
$20~\text{k}\Omega$	19.999 k <b>Ω</b>	0.5% + 3	1.5% + 5	-
2000 Ω	1999.9 Ω	0.5% + 3	1.5% + 5	-
200 Ω	199.99 Ω	0.8% + 5	2.0% + 10	After short cal.
20 Ω	$19.999\Omega$	1.2% + 40	2.5% + 200	After short cal.

Specifications are based on measurements performed at the test sockets and on battery operation.
 DUT and test leads need to be properly shielded by connecting to the guard terminal, if necessary.

# Capacitance (Parallel Mode), Test Frequency = 100 Hz/120 Hz

		Accuracy		_
Range	Maximum Display	Capacitance	DF	Note
10 mF	19.99 mF [1]	3.0% + 5 (DF<0.1)	10% + 100/Cx + 5 (DF<0.1)	After short cal.
1000 μF	1999.9 μF [2]	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After short cal.
200 μF	199.99 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
20 μF	19.999 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
2000 nF	1999.9 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
200 nF	199.99 nF	0.7% + 5 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	After open cal.
20 nF	19.999 nF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After open cal.

## Capacitance (Parallel Mode), Test Frequency = 1 kHz

			Accuracy	
Range	Maximum Display	Capacitance	DF	Note
1 mF	1.999 mF [1]	3.0% + 5 (DF<0.1)	10% + 100/Cx + 5 (DF<0.1)	After short cal.
200 μF	199.99 μF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After short cal.
20 μF	19.999 μF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
2000 nF	1999.9 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
200 nF	199.99 nF	0.7% + 3 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	-
20 nF	19.999 nF	0.7% + 5 (DF<0.5)	0.7% + 100/Cx + 5 (DF<0.5)	After open cal.
2000 pF	1999.9 pF	1.0% + 5 (DF<0.1)	2.0% + 100/Cx + 5 (DF<0.1)	After open cal.

# Capacitance (Parallel Mode), Test Frequency = 10 kHz

	Accuracy			
Range	Maximum Display	Capacitance	DF	Note
50 μF	50.0 μF	3.0% + 8 (DF<0.1)	12.0% + 100/Cx + 10 (DF<0.1)	After short cal.
20 μF	19.999 μF	3.0% + 6 (DF<0.2)	5.0% + 100/Cx + 8 (DF<0.2)	After short cal.
2000 nF	1999.9 nF	1.5% + 5 (DF<0.5)	1.5% + 100/Cx + 6 (DF<0.5)	-
200 nF	199.99 nF	1.5% + 5 (DF<0.5)	1.5% + 100/Cx + 6 (DF<0.5)	-
20 nF	19.999 nF	1.5% + 5 (DF<0.5)	1.5% + 100/Cx + 6 (DF<0.5)	-
2000 pF	1999.9 pF	2.0% + 6 (DF<0.5)	3.0% + 100/Cx + 6 (DF<0.1)	After open cal.
200pF	199.99 pF	3.0% + 8 (DF<0.1)	5.0% + 100/Cx + 8 (DF<0.1)	After open cal.

<sup>1.</sup> This reading can be extended up to 1999 MAX display with accuracy that is not specified

<sup>2.</sup> This reading can be extended up to 19999 MAX display with accuracy that is not specified.

<sup>3.</sup> Q value is the reciprocal of DF.

<sup>4.</sup> Cx = Counts of displayed C value. E.g., If C = 88.88  $\mu$ F then Cx = 8888.

<sup>5.</sup> Specifications are based on measurements performed at the test sockets and on battery operation.

<sup>6.</sup> DUT and test leads need to be properly shielded by connecting to the guard terminal, if necessary.

# Inductance (Series Mode), Test Frequency = 100 Hz/120 Hz

		Accu	Accuracy	
Range	Maximum Display	Inductance	DF	Note
1000 H	999.9 H	1.0% + (Lx/10000)% + 5	2.0% + 100/Lx + 5	After open cal.
200 H	199.99 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
20 H	19.999 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
2000 mH	1999.9 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
200 mH	199.99 mH	1.0% + (Lx/10000)% + 5	3.0% + 100/Lx + 5	After short cal.
20 mH	19.999 mH	2.0% + (Lx/10000)% + 5	10.0% + 100/Lx + 5	After short cal.

# Inductance (Series Mode), Test Frequency = 1 kHz

		Асси	Accuracy	
Range	Maximum Display	Inductance	DF	Note
100 H	99.99 H	1.0% + (Lx/10000)% + 5	2.0% + 100/Lx + 5	After open cal.
20 H	19.999 H	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
2000 mH	1999.9 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	
200 mH	199.99 mH	0.7% + (Lx/10000)% + 5	1.2% + 100/Lx + 5	-
20 mH	19.999 mH	1.0% + (Lx/10000)% + 5	3.0% + 100/Lx + 5	After short cal.
2000 μΗ	1999.9 μΗ	2.0% + (Lx/10000)% + 5	10.0% + 100/Lx + 5	After short cal.

# Inductance (Series Mode), Test Frequency = 10 kHz

		Accu		
Range	Maximum Display	Inductance	DF	Note
1000 mH	999.9 mH	2.0% + (Lx/10000)% + 8	2.0% + 100/Lx + 10	-
200 mH	199.99 mH	1.5% + (Lx/10000)% + 8	2.0% + 100/Lx + 10	-
20 mH	19.999 mH	1.5% + (Lx/10000)% + 10	3.0% + 100/Lx + 15	After short cal.
2000 μΗ	1999.9 μΗ	2.0% + (Lx/10000)% + 10	8.0% + 100/Lx + 20	

Q value is the reciprocal of DF.
 Lx = counts of displayed L value. E.g., If L = 88.88 H, then Lx = 8888.

<sup>3.</sup> Specifications are based on measurements performed at the test sockets and on battery operation.

<sup>4.</sup> DUT and test leads need to be properly shielded by connecting to the guard terminal, if necessary.

# General Specifications

Parameter	U1731A/U1731B	U1731A/U1731B		U1732A/U1732B		
Measurements	L/C/R/D/Q	L/C/R/D/Q		L/C/R/D/Q/q		
Tolerance mode	1%, 5%, 10%		1%, 5%, 10%, 20%			
Test frequency (Accuracy = ±0.1% of actual test frequency)	Test frequency setting 120 Hz 1 kHz	Actual test frequency 120 Hz 1010 Hz	Test frequency setting 100 Hz 120 Hz 1 kHz 10 kHz	Actual test frequency 100 Hz 120 Hz 1010 Hz 9.6 kHz		
Measuring circuit mode	Inductance (L): Defaults to series mode Capacitance/Resistance (C/R): Defaults to parallel mode					
Display	L/C/R : Maximum display 19999 D/Q: Maximum display 999 (Auto range)					
Backlight	Available for model U1732A/U1732B					
Ranging mode	Auto and Manual					
Test signal level	~0.6 V <sub>RMS</sub>					
Measurement rate	1 reading/s, nominal					
Response time	~1 s/DUT (manual range)					
Auto power-off	~5 mins without operation					
Power supply	<ul> <li>9 V Alkaline battery (ANSI/NEDA 1604A or IEC 6LR61)</li> <li>AC power adapter and cord available as options</li> </ul>					
Power consumption	<ul><li>~40 mA (on battery operation)</li><li>0.08 mA after auto power-off</li></ul>					
nput protection fuse 0.1 A/250 V						
Battery life	7 hours (typical) without backlight and based on new alkaline					
Low battery indicator	+ — will appear when the voltage drops below ~ 6.8 V					
Operating environment	0 °C to 40 °C; 0 to 70% relative humidity (R.H.)					
Storage environment	-20 °C to 50 °C; 0 to 80% R.H. non-condensing					
Temperature coefficient	0.15 x (specified accuracy)/°C (0 °C to 18 °C or 28 °C to 40 °C)					
Weight	330 g					
Dimensions (H x W x D)	184 mm x 87 mm x 41 mm					
Safety and EMC compliance         IEC 61010-1:2001/EN 61010-1:2001 (2nd Edition) Pollution Degree 2, IEC 61326-EN 61326-2-1:2006, ICES-001:2004, AS/NZS CISPR11:2004						
Calibration	One-year calibration cycle recommended					

# Ordering Information



## Standard shipped items

Standard U1731A, U1731B, U1732A and U1732B ordering include:

- Quick Start Guide
- Certificate of Calibration (CoC)
- Alligator clip leads
- 9 V Alkaline battery

Option U1731A-SMD and U1732A-SMD ordering includes (For A series handheld LCR meters only) : SMD tweezer and soft carrying case in addition to the standard shipped items

### Recommended accessories



U1174A Soft carrying case



U5481A IR-to-USB cable



U1782A SMD tweezer



**U1780A** Power adapter and cord (according to country)



U1781A Alligator clip leads

## **Evolving Since 1939**

Our unique combination of hardware, software, services, and people can help you reach your next breakthrough. We are unlocking the future of technology. From Hewlett-Packard to Agilent to Keysight.







### myKeysight

### myKeysight

### www.keysight.com/find/mykeysight

A personalized view into the information most relevant to you.

### http://www.keysight.com/find/emt\_product\_registration

Register your products to get up-to-date product information and find warranty information.

KEYSIGHT SERVICES
Accelerate Technology Adoption.
Lower costs.

### **Keysight Services**

### www.keysight.com/find/service

Keysight Services can help from acquisition to renewal across your instrument's lifecycle. Our comprehensive service offerings—onestop calibration, repair, asset management, technology refresh, consulting, training and more—helps you improve product quality and lower costs.



### Keysight Assurance Plans

### www.keysight.com/find/AssurancePlans

Up to ten years of protection and no budgetary surprises to ensure your instruments are operating to specification, so you can rely on accurate measurements.

### Keysight Channel Partners

### www.keysight.com/find/channelpartners

Get the best of both worlds: Keysight's measurement expertise and product breadth, combined with channel partner convenience.

ATCA ®, AdvancedTCA®, and the ATCA logo are registered US trademarks of the PCI Industrial Computer Manufacturers Group.

www.keysight.com/find/handheldlcr

For more information on Keysight Technologies' products, applications or services, please contact your local Keysight office. The complete list is available at: www.keysight.com/find/contactus

#### Americas

Canada (877) 894 4414 Brazil 55 11 3351 7010 Mexico 001 800 254 2440 United States (800) 829 4444

#### Asia Pacific

Australia 1 800 629 485 800 810 0189 China Hong Kong 800 938 693 India 1 800 11 2626 0120 (421) 345 Japan 080 769 0800 Korea 1 800 888 848 Malaysia Singapore 1 800 375 8100 0800 047 866 Taiwan Other AP Countries (65) 6375 8100

### Europe & Middle East

For other unlisted countries: www.keysight.com/find/contactus (BP-9-7-17)

Opt. 3 (IT)

0800 0260637



United Kingdom

### www.keysight.com/go/quality

Keysight Technologies, Inc. DEKRA Certified ISO 9001:2015 Quality Management System

