

## UNIVERSAL LEAD SET

The 3Ø Universal lead set simplifies connecting to any transformer. The durable kelvin clamps extend up to 3" for connecting to any bushing size. Lead spans range from 5m (15ft) to 30m (100ft), ensuring you can connect and test any transformer configuration. All of the leads can be connected in one ladder climb, reducing the risk of fall injuries.

The kelvin clamps also accept safety banana plugs, making it easy to connect the 3Ø lead set to a CT terminal block. Electrical shock and potential markings are clearly displayed on the clamp, informing operators how to connect safely and securely.

The TTRU3 lead set can be used with most existing MTOs, MWAs, and TTRs. Requires PNs

- 2008-009 - H lead breakout
- 2008-010 - X lead breakout




You can even use your old lead set with the TTRU3! Applies to PNs

H leads:

- 2008-001-XX
- 2008-002-XX
- 2008-003-XX
- 2008-004-XX

X-leads:


- 2008-005-XX
- 2008-006-XX
- 2008-007-XX
- 2008-008-XX




Color-coded Connectors

Color-coded Clamps

*H Leads*



*X Leads*



## ORDERING INFORMATION

Item (Qty)	Cat. No.	Item (Qty)	Cat. No.
3Ø Transformer Turns Ratio Test Set	TTRU3-BASIC	<b>Accessories Required for Operation</b>	
<b>Included Accessories</b>		<b>Lead P/Ns 2008-XXX-XX (8 total) can be used with the TTRU3 and qualify as required accessories</b>	
AC Adapters & Power Cord - 2.5m (8ft)	2009-874	3Ø universal shielded test lead sets compatible with MTO3XX, MWA3XX, TTRU3 instruments (up to 10A max), complete with color-coded Kelvin Clamps: Choose Kit or mix & match H & X	
OLTC Tap Changer cable - 9m (30ft)	1011-622	5m (15ft) H & X	2008-15KIT2
Cable bag - backpack	2012-180	9m (30ft) H & X	2008-30KIT2
Ground Cable - 5m (16ft)	1011-352	18m (60ft) H & X	2008-60KIT2
Thumb Drive	1011-585	30m (100ft) H & 18m (60ft) X	2008-100KIT2
Triple Function Pen	2011-538	5m (15ft) H	2008-300-15
<b>Optional Hardware Accessories</b>		5m (15ft) X	2008-301-15
1:1 Test Jig	2005-249	9m (30ft) H	2008-300-30
Safety Beacon – 18m (60ft)	1004-639	9m (30ft) X	2008-301-30
Transit Case (for instrument)	2012-236	18m (60ft) H	2008-300-60
TRS1+ Calibration Standard	TRS1PLUS	18m (60ft) X	2008-301-60
Calibration Certificate	CERT-NIST	30m (100ft) H	2008-300-100
USB Printer	90029-573	<b>Optional Lead Accessories</b>	
USB Printer Paper (x48 rolls)	90029-573-P	9m (30ft) H extensions	2008-300-30X
OLTC Tap Changer cable adapters	1011-622-A	9m (30ft) X extensions	2008-301-30X
<b>Software Options</b>		9m (30ft) H & 9m (30ft) X extensions	2008-30XKIT2
AutoOLTC	SW-AUTOOLTC		
Magnetic Balance	SW-MAGNETICBAL		