



Hot air iron set with safety rest

Item No: T0052711799N

Hot air iron set with safety rest

KEY FEATURES

- + 200 W, 24 V
- + Temperature range from 50 °C - 550 °C
- + Activated by finger switch
- + Cannot be used with the WR2 rework systems

TECHNICAL DATA

ESD Safe	Yes
Hot Air (picto)	Yes
Maximum Hot Air Flow Rate l/min (Depends on Tool)	15 l/min
Power	200 W
Silver Line Heating Element Technology	Yes
Supply Unit	WR3M WR3ME
Temperature Accuracy °C	± 26 °C
Temperature Accuracy °F	±26.66 °C
Temperature Range (Depends on Tool)	199 - 998°F
Temperature Range °C	93 - 537 °C
Temperature Range °F	199 - 998 °F
Tip Range	F R D Q
Tip Type	F R D & Q Series
UPC	037103304605